



IMPORTANT NOTICE

TO INSURE A LONGER LIFE FOR YOUR CERAMIC PAD HEATER, DO NOT INSULATE PAST THE CHANGE IN COLOR ON THE TAIL BEADS OF THE HEATER.

THE TAILS OF THIS HEATER ARE CONSTRUCTED BY WELDING NICKEL WIRE TO THE HEATER WIRE ELEMENT TO ALLOW FOR A COLD TAIL. THE CHANGE IN COLOR INDICATES WHERE THE WELD IS AND EXCESS HEAT COULD CAUSE THE NICKEL TO BECOME BRITTLE AND THIS MAY SHORTEN ITS LIFE.

REV.	DESCRIPTION	DR.	DATE	DATE	DATE																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;">DATE</td> <td style="width: 10%;">N.T.S.</td> <td style="width: 10%;">BY</td> <td style="width: 10%;">EHS</td> <td style="width: 10%;">DATE</td> <td style="width: 10%;">8/2/99</td> </tr> <tr> <td>REVISION</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>NO.</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="6" style="text-align: center;">TYPICAL</td> </tr> </table>						DATE	N.T.S.	BY	EHS	DATE	8/2/99	REVISION						NO.						TYPICAL					
DATE	N.T.S.	BY	EHS	DATE	8/2/99																								
REVISION																													
NO.																													
TYPICAL																													
EHS INC. ELECTRIC HEATING SYSTEMS ROBINNSVILLE, NJ																													
COLD TAIL WELD INFO:																													
SHEET NO. 1 OF 1 DRAWING NO. A-1013																													